



Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	:	_____	Inspection Date	:	2024-05-02
Tel.	:	_____	Lemon Inspection ID	:	LEMON24050001
Inspector	:	Aekkawit Tee Bunleng	Approved By	:	sakulpong singnarong

Details

Brand	MERCEDES BENZ	Model year	2019
Model	C43	Engine Code - No.	27682330977036
Sub-model	AMG 4MATIC COUPE (CKD)	Registration year	2019-04-03
Registration No.		Chassis No.	WDD2053646L044272
Current Mileage(km.)	30837	Engine Capacity(cc.)	3000

Inspection Lists

Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected SCHIC INSPECTION BY LEMON-AIDE


Inspector

Aekkawit Tee Bunleng


Approved By




Vehicle Front Image




Vehicle Rear Left Image




Vehicle Registration Book



Vehicle Odometer Image




Vehicle Back Image




Vehicle Front Right Image




OBD Vehicle Identity Analysis




Vehicle Engine Image



Vehicle Rear Right Image




Passenger Back Seat Image




Vehicle Front Left Image



OBD Vehicle Health Analysis



Passenger Front Console Image




Vehicle Engine Number Image




Vehicle Chassis Image




Passenger Ceiling Part Image



Passenger Front Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front Windshield	O
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	O	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O (S1)
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front right door	BP (S1)	22. Rear Skirt	O
10. Rear right door	BP	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		



Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing


Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices






Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2821	5
2. Front Right Tire Condition	Normal	2821	5
3. Back Left Tire Condition	Worn Down	0220	4
4. Back Right Tire Condition	Worn Down	0220	4



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.22
3. Charging Voltage(V.)	14.25

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

















Chassis Damage Level	No Damage
----------------------	-----------








Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Console	
2. Dashboard	
3. Steering wheel and control panel	
4. Sound system and monitor	
5. Air conditioning system	
6. Front left door panel	
7. Left power window master	
8. Front left seat	
9. Front right seat	
10. Window control switch, front right door	
11. Front right door panel	
12. Right rear door panel	
13. Right rear power window master switch	
14. Rear Seat 1	
15. Rear Seat 2	
16. Rear Seat 3	

17. Left rear power window master switch	
18. Left rear door panel	
19. Luggage storage area	
20. Gear knob	
21. Left Headliner	
22. Right Headliner	
23. Rear	

Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		



Flood Report

Evidence of Flood	No
-------------------	----



Fire Report

Evidence of Fire	No
------------------	----



Inspector Note**Vehicle :** MERCEDES BENZ C43**Chassis number :** WDD2053646L044272**Inspection date :** 2024-05-02

Inspector : ภายนอก : พบหลักฐานการทำสีเก็บสีบางส่วนคือ ประตูขวา แก้มหลังขวา , ประตูหน้าขวามีรอยขีดข่วนเล็กน้อย ฝาท้ายมีรอยขีดข่วนเล็กน้อย สภาพยางเสื่อมสภาพทั้ง 4 ล้อ ภายใน : ภายในโดยรวมสะอาดเรียบร้อย อุปกรณ์ไฟฟ้าทำงานได้ปกติ เครื่องยนต์ : ไม่สามารถถ่ายเลขเครื่องยนต์ได้ เครื่องยนต์ทำงานได้ครบปกติ ตรวจสอบด้วย OBD พบ CodeU012287STORED Communication with control unit "Traction system" has a malfunction. The message is missing P1C5C00 STORED Battery discharge protection is activated B226656 STORED The drive authorization data are implausible.An incorrect or incompatible configuration was detected แนะนำให้นำรถไปรีเซ็ตระบบกับทางศูนย์บริการเนื่องจากรถไม่ค่อยได้ใช้งาน โครงสร้าง : โครงสร้างหลักปกติ ไม่พบอุบัติเหตุถึงโครงสร้างหรือหลักฐานการซ่อมแซมโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE