



Preowned Vehicle Inspection Report

Premium Inspection Analysis

| | | | |
|---------------|--|---------------------|------------------|
| Customer Name | : MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD. | Inspection Date | : 2024-05-08 |
| Tel. | _____ | Lemon Inspection ID | : LEMON24050083 |
| Inspector | : tanruk tipin | Approved By | : : tanruk tipin |

Details

| | | | |
|----------------------|---------------|----------------------|-------------------|
| Brand | MERCEDES BENZ | Model year | 2022 |
| Model | A200 | Engine Code - No. | 28291430608842 |
| Sub-model | AMG Dynamic | Registration year | 2022-06-24 |
| Registration No. | _____ | Chassis No. | W1K1771876L002304 |
| Current Mileage(km.) | 50065 | Engine Capacity(cc.) | 1300 |

Inspection Lists

Grading

| | |
|------------------------|-------|
| 1. Exterior | ★★★★★ |
| 2. Chassis | ★★★★★ |
| 3. Interior | ★★★★★ |
| 4. Engine & Mechanical | ★★★★★ |
| 5. Overall | ★★★★★ |


This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector tanruk tipin Approved By tanruk tipin

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image



Vehicle Rear Right Image




Vehicle Registration Book



Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis




OBD Vehicle Health Analysis




Passenger Front Console Image




Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



| Exterior Status | |
|-----------------|--------------------|
| O | Original |
| N | New Parts |
| BP | New Body Paint Job |
| X | Need Replacing |

Exterior Inspection Report

| | | | |
|-----------------------|--------|-----------------------|--------|
| 1. Front Skirt | N | 14. Left Skirt | O |
| 2. Front Bumper | O | 15. Left Wing Mirror | O |
| 3. Front Right Fender | BP | 16. Front Windshield | O |
| 4. Front Right Wheel | O | 17. Roof | O |
| 5. Front Left Fender | O | 18. Rear Right Fender | O |
| 6. Front Left Wheel | O | 19. Rear Bonnet | O (S1) |
| 7. Front bonnet | BP | 20. Back Right Wheel | O |
| 8. Right Wing Mirror | O | 21. Rear Bumper | O |
| 9. Front right door | O (S1) | 22. Rear Skirt | O |
| 10. Rear Right Door | O | 23. Rear Left Fender | O |
| 11. Right Skirt | O | 24. Back Left Wheel | O |
| 12. Rear Left door | O (S1) | 25. Back Windshield | O |
| 13. Front Left Door | O | | |

Main Status

| | |
|----|--------------------|
| BP | New Body Paint Job |
| N | New Parts |
| O | Original |
| X | Need Replacing |


Sub Status

| | | | |
|---|-----------|---|---------------------|
| S | Scratched | G | Stone Chip on Glass |
| D | Dent | Y | Cracked |
| R | Rust | E | Dimple |
| C | Corrosion | F | Paint Fade |



Vehicle Defect Notices



Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


| Conditions Report | Tire Status | Date Code | Tire Depth(mm) |
|-------------------------------|-------------|-----------|----------------|
| 1. Front Left Tire Condition | Normal | 0921 | 4 |
| 2. Front Right Tire Condition | Normal | 1021 | 4 |
| 3. Back Left Tire Condition | Normal | 1021 | 5 |
| 4. Back Right Tire Condition | Normal | 1222 | 5 |



Battery Condition Report

| Conditions Report | Details |
|-------------------------|---------|
| 1. Battery Status | Pass |
| 2. Resting Voltage(V.) | 12 |
| 3. Charging Voltage(V.) | 14 |

Chassis Report




| Damage Level |
|--------------|
| No Damage |
| Level A |
| Level B |
| Level C |

| | |
|---|------|
| No dent in the under carriage (th) | PASS |
| No deform chassis or chassis frame (th) | PASS |
| No visible corrosion on the chassis or chassis frame (th) | PASS |
| No missing part on the chassis frame (th) | PASS |
| Half cut Analysis (th) | PASS |

















| | |
|----------------------|-----------|
| Chassis Damage Level | No Damage |
|----------------------|-----------|








Interior Inspection Points



| | |
|-----------------------------|---|
| Scratched/Faded items | S |
| Sunken/Sagging car seats | D |
| Tear/Cracks | Y |
| Failed Electrical Equipment | E |

Interior Report

| | |
|---|--|
| 1. Console |  |
| 2. Dashboard |  |
| 3. Steering wheel and control panel |  |
| 4. Sound system and monitor |  |
| 5. Air conditioning system |  |
| 6. Front left door panel |  |
| 7. Left power window master |  |
| 8. Front left seat |  |
| 9. Front right seat |  |
| 10. Window control switch, front right door |  |
| 11. Front right door panel |  |
| 12. Right rear door panel |  |
| 13. Right rear power window master switch |  |
| 14. Rear Seat 1 |  |
| 15. Rear Seat 2 |  |
| 16. Rear Seat 3 |  |



| | |
|--|--|
| 17. Left rear power window master switch |  |
| 18. Left rear door panel |  |
| 19. Luggage storage area |  |
| 20. Gear knob |  |
| 21. Left Headliner |  |
| 22. Right Headliner |  |
| 23. Rear |  |

Vehicle Overview

| | | | |
|--|------|--|------|
| 1. Vehicle Engine Number Analysis (th) | PASS | 14. Air Conditioning and Heating System (th) | PASS |
| 2. Vehicle Chassis Number Analysis (th) | PASS | 15. Front and Rear Suspension (th) | PASS |
| 3. Vehicle Original OEM Color Analysis (th) | PASS | 16. Drive Axle (th) | PASS |
| 4. Engine System (th) | PASS | 17. High Tech (th) | PASS |
| 5. Transmission System (th) | PASS | 18. Passenger Comfort (th) | PASS |
| 6. Electrical System (th) | PASS | 19. Security System (th) | PASS |
| 7. Brake System (th) | PASS | 20. Safety Active (th) | PASS |
| 8. Steering System (th) | PASS | 21. Safety Passive (th) | PASS |
| 9. Fuel System (th) | PASS | 22. Original Mileage Analysis (th) | PASS |
| 10. Four-wheel Drive (th) | PASS | 23. Overall Chassis Analysis (th) | PASS |
| 11. Turbocharger/Supercharger (th) | PASS | 24. Overall Exterior Analysis (th) | PASS |
| 12. Fuel Injection and Engine Management System (th) | PASS | 25. Overall Interior Analysis (th) | PASS |
| 13. Engine Cooling System (th) | PASS | | |


Flood Report

| | |
|-------------------|----|
| Evidence of Flood | No |
|-------------------|----|



Fire Report

| | |
|------------------|----|
| Evidence of Fire | No |
|------------------|----|



Inspector Note**Vehicle :** MERCEDES BENZ A200**Chassis number :** W1K1771876L002304**Inspection date :** 2024-05-08

Inspector : # Mercedes-Benz A 200 AMG Dynamic ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมพบหลักฐานการซ่อมแซมเก็บบงานสี ฟากระโปรงหน้า แก้วหน้าขวา กันชนหน้าเปลี่ยนชิ้น / สภาพยางปกติทั้ง 4 เส้น / คันจับแรงหน้ามีรอยถอดซ่อม โดยรวม รวดสวย พร้อมใช้งาน ภายใน(Interior) : ภายใน แผงประตูหลังซ้ายมีคราบเปื้อนเล็กน้อย เบาะหน้าซ้ายและหลังซ้ายมีคราบเปื้อนเล็กน้อย , อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ

เครื่องยนต์(Engine) : เครื่องยนต์ทำงานปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิดปกติ (ไม่ได้ทดสอบขับขี่)

โครงสร้าง(Frame) : ตรวจสอบไม่พบอุบัติเหตุถึงโครงสร้าง ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE