



# Preowned Vehicle Inspection Report

Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-06-18
Tel.	:	Lemon Inspection ID	: LEMON24060183
Inspector	: Porramaet Tam Jaichoen	Approved By	: Tanrak T

### Details

Brand	MERCEDES BENZ	Model year	2019
Model	GLA	Engine Code - No.	27091031791657
Sub-model	200 URBAN	Registration year	2019-08-07
Registration No.		Chassis No.	WDC1569436L011166
Current Mileage(km.)	139045	Engine Capacity(cc.)	1600

### Inspection Lists

### Grading

1. Exterior	★★★★★
2. Chassis	★★★★★
3. Interior	★★★★★
4. Engine & Mechanical	★★★★★
5. Overall	★★★★★

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.


Inspector

*Porramaet Tam Jaichoen*

Approved By

*Tanrak T*

Vehicle Front Image



Vehicle Back Image



Vehicle Front Left Image



Vehicle Front Right Image






Vehicle Rear Left Image




Vehicle Rear Right Image



**Vehicle Registration Book**




**Vehicle Engine Image**





Vehicle Odometer Image



Vehicle Chassis Image



**Vehicle Engine Number Image**




**OBD Vehicle Identity Analysis**







**OBD Vehicle Health Analysis**




**Passenger Front Console Image**




**Passenger Front Seat Image**



**Passenger Ceiling Part Image**




**Passenger Back Seat Image**





**Exterior Inspection Points**



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

## Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	BP (S2)	15. Left Wing Mirror	O
3. Front Right Fender	O	16. Front windshield	N
4. Front Right Wheel	O	17. Roof	O
5. Front Left Fender	BP (S1)	18. Rear Right Fender	O
6. Front Left Wheel	O	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back Right Wheel	O
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front Right Door	O	22. Rear Skirt	O
10. Rear Right Door	O	23. Rear Left Fender	O
11. Right Skirt	O	24. Back Left Wheel	O
12. Rear Left Door	O	25. Back Windshield	O
13. Front Left Door	O		

### Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

### Sub Status


S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

**Vehicle Defect Notices**









**Vehicle Defect Notices**



**Tire Condition Report**


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Worn Down	1621	4
2. Front Right Tire Condition	Worn Down	1021	5
3. Back Left Tire Condition	Worn Down	1021	5
4. Back Right Tire Condition	Normal	1721	5



**Battery Condition Report**

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.4
3. Charging Voltage(V.)	13.4

## Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS

Chassis Damage Level	No Damage
----------------------	-----------


























### Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

**Interior Report**

1. Console	
2. Dashboard	
3. Steering wheel and control panel	
4. Sound system and monitor	
5. Air conditioning system	
6. Front left door panel	
7. Left power window master	
8. Front left seat	
9. Front right seat	
10. Window control switch, front right door	
11. Front right door panel	
12. Right rear door panel	
13. Right rear power window master switch	
14. Rear Seat 1	
15. Rear Seat 2	
16. Rear Seat 3	

17. Left rear power window master switch	
18. Left rear door panel	
19. Luggage storage area	
20. Gear knob	
21. Left Headliner	
22. Right Headliner	
23. Rear	



### Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		





**Flood Report**

Evidence of Flood	No
-------------------	----



**Fire Report**

Evidence of Fire	No
------------------	----



**Inspector Note****Vehicle :** MERCEDES BENZ GLA**Chassis number :** WDC1569436L011166**Inspection date :** 2024-06-18

**Inspector :** ภายนอก(Exterior) : จากการตรวจพบร่องรอยการทำสีรอบคัน พบรอยถลอกบริเวณกันชนหน้า พบรอยขีดข่วนเล็กน้อยรอบคัน เปลี่ยนกระจกหน้าใหม่ ยางเสื่อมสภาพทั้ง 4 เส้น ยางปี 21 ภายใน(Interior) : ภายในพบรอยเจิมแป้น ระบบไฟส่องสว่างใช้งานได้ปกติ แอร์วิทยุใช้งานได้ปกติ เครื่องยนต์(Electric) : เครื่องยนต์พบคราบน้ำมัน เครื่องชี้เล็กน้อย วิเคราะห์ด้วย OBD พบโค้ด P13C523 เกี่ยวกับแรงดันไฟ โครงสร้าง(Frame) : โครงสร้างหลักปกติ ไม่พบร่องรอยซ่อมแซมโครงสร้าง

**Vehicle Certification :** Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE