

Premium Inspection Analysis



Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-06-25
Tel.	:	Lemon Inspection ID	: LEMON24060257
Inspector	: แทนรัก ทอย ทิพย์อินทร์	Approved By	: Chaimongkol C

#### **Details**

Brand	MERCEDES BENZ	Model year	2018
Model	C200	Engine Code - No.	26491530043511
Sub-model	COUPE AMG DYNAMIC	Registration year	2019-10-28
Registration No.		Chassis No.	WDD2053776L043159
Current Mileage(km.)	131872	Engine Capacity(cc.)	1500

Inspection Lists	Grading
1. Exterior	****
2. Chassis	****
3. Interior	****
4. Engine & Mechanical	****
5. Overall	****

This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector	ELIMIN NOO MMOOMIN	Approved By	
المحمد حاجمه	แทนรัก ทอย ทิพย์อินทร์	Amaran and Dec	Chainmakol, C.



Premium Inspection Analysis

#### Vehicle Front Image



#### Vehicle Back Image





Premium Inspection Analysis

#### Vehicle Front Left Image



#### Vehicle Front Right Image






Premium Inspection Analysis

#### Vehicle Rear Left Image




#### Vehicle Rear Right Image






Premium Inspection Analysis

#### **Vehicle Registration Book**



#### Vehicle Engine Image







Premium Inspection Analysis

#### Vehicle Odometer Image




#### Vehicle Chassis Image






Premium Inspection Analysis

#### Vehicle Engine Number Image




#### **OBD Vehicle Identity Analysis**






Premium Inspection Analysis

## OBD Vehicle Health Analysis



#### Passenger Front Console Image








Premium Inspection Analysis

#### Passenger Front Seat Image



#### Passenger Ceiling Part Image





Premium Inspection Analysis

# Passenger Back Seat Image








Premium Inspection Analysis

#### **Exterior Inspection Points**



Exterior Status		
0	Original	
N	New Parts	
BP	New Body Paint Job	
Χ	Need Replacing	



Premium Inspection Analysis

#### **Exterior Inspection Report**

1. Front Skirt	0	14. Left Skirt	0
2. Front Bumper	O (S2,Y)	15. Left Wing Mirror	0
3. Front Right Fender	0	16. Front windshield	O (G1)
4. Front Right Wheel	O (S1)	17. Roof	0
5. Front Left Fender	O (S2)	18. Rear right fender	O (D2)
6. Front Left Wheel	0	19. Rear Bonnet	O (D2)
7. Front bonnet	O (G1)	20. Back Right Wheel	0
8. Right Wing Mirror	0	21. Rear Bumper	BP (S1)
9. Front right door	O (D1)	22. Rear Skirt	0
10. Rear Right Door	0	23. Rear left fender	O (D2)
11. Right Skirt	0	24. Back left wheel	O (S1)
12. Rear Left Door	0	25. Back Windshield	0
13. Front left door	O (D1)		

#### **Main Status**


BP	New Body Paint Job
N	New Parts
0	Original
Χ	Need Replacing


#### **Sub Status**

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	Е	Dimple
С	Corrosion	F	Paint Fade




Premium Inspection Analysis









Premium Inspection Analysis








Premium Inspection Analysis









Premium Inspection Analysis







Premium Inspection Analysis








Premium Inspection Analysis







Premium Inspection Analysis

#### Tire Condition Report

Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2721	4
2. Front Right Tire Condition	Normal	2721	5
3. Back Left Tire Condition	Worn Down	0823	3
4. Back Right Tire Condition	Worn Down	0823	3










## Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12
3. Charging Voltage(V.)	14



Premium Inspection Analysis

#### Chassis Report



# Damage Level

No Damage

Level A

Level B

Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS


Chassis Damage Level	No Damage
----------------------	-----------





Premium Inspection Analysis

## Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E



Premium Inspection Analysis

## Interior Report

1. Console	
2. Dashboard	
3. Steering wheel and control panel	
4. Sound system and monitor	
5. Air conditioning system	
6. Front left door panel	
7. Left power window master	
8. Front left seat	
9. Front right seat	
10. Window control switch, front right door	
11. Front right door panel	
12. Right rear door panel	
13. Right rear power window master switch	
14. Rear Seat 1	
15. Rear Seat 2	
16. Rear Seat 3	



Premium Inspection Analysis

17. Left rear power window master switch	
18. Left rear door panel	
19. Luggage storage area	
20. Gear knob	
21. Left Headliner	
22. Right Headliner	
23. Rear	



Premium Inspection Analysis

## Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		



Premium Inspection Analysis

## Flood Report

#### Evidence of Flood







# Fire Report

#### Evidence of Fire

No







Premium Inspection Analysis

#### **Inspector Note**

Vehicle: MERCEDES BENZ C200

Chassis number: WDD2053776L043159

Inspection date: 2024-06-25

Inspector: ภายนอก(Exterior): การตรวจสภาพภายนอกโดยรวม ไม่พบหลักฐานการช่อมแซมทำสี ริ้วรอยถลอกบุบ รอบคัน กันชนหน้าเป็นรอยแตก / สภาพยางหน้าปี 21 ยางหลังปี 23 เสื่อมสภาพ ล้อหลังขวาเป็นรอยถลอกเล็กน้อย ภายใน(Interior): ภายใน ที่บังแดดเป็นคราบแป้ง เบาะเป็นรอยย่นเล็กน้อย,อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้ สมบูรณ์ครบปกติ เครื่องยนต์(Engine): เครื่องยนต์ทำงานได้ปกติ วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิด ปกติ (ไม่ได้ทดสอบขับขี่) โครงสร้าง(Frame): อุบัติเหตุไม่มี โครงสร้างหลักปกติ ไม่มีการช่อมแซมโครงสร้างหรือมีการ ชนถึงโครงสร้าง

Vehicle Certification: Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE