


Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image



Vehicle Front Right Image




Vehicle Rear Left Image



Vehicle Rear Right Image




Vehicle Registration Book




Vehicle Engine Image



Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis




OBD Vehicle Health Analysis




Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



| Exterior Status | |
|-----------------|--------------------|
| O | Original |
| N | New Parts |
| BP | New Body Paint Job |
| X | Need Replacing |

Exterior Inspection Report

| | | | |
|-----------------------|--------|-----------------------|--------|
| 1. Front Skirt | O | 14. Left Skirt | O |
| 2. Front Bumper | O (S1) | 15. Left Wing Mirror | O |
| 3. Front Right Fender | O | 16. Front windshield | O (G1) |
| 4. Front Right Wheel | O | 17. Roof | O |
| 5. Front Left Fender | O | 18. Rear Right Fender | O |
| 6. Front Left Wheel | O | 19. Rear Bonnet | O |
| 7. Front bonnet | O (S1) | 20. Back Right Wheel | O |
| 8. Right Wing Mirror | O | 21. Rear Bumper | O |
| 9. Front Right Door | O | 22. Rear Skirt | O |
| 10. Rear right door | O (S1) | 23. Rear left fender | BP |
| 11. Right Skirt | O | 24. Back Left Wheel | O |
| 12. Rear Left door | BP | 25. Back Windshield | O |
| 13. Front left door | BP | | |

Main Status

| | |
|----|--------------------|
| BP | New Body Paint Job |
| N | New Parts |
| O | Original |
| X | Need Replacing |

Sub Status

| | | | |
|---|-----------|---|---------------------|
| S | Scratched | G | Stone Chip on Glass |
| D | Dent | Y | Cracked |
| R | Rust | E | Dimple |
| C | Corrosion | F | Paint Fade |

Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


| Conditions Report | Tire Status | Date Code | Tire Depth(mm) |
|-------------------------------|-------------|-----------|----------------|
| 1. Front Left Tire Condition | Normal | 2822 | 4 |
| 2. Front Right Tire Condition | Normal | 2322 | 5 |
| 3. Back Left Tire Condition | Bald Tire | 2021 | 4 |
| 4. Back Right Tire Condition | Bald Tire | 2021 | 4 |



Battery Condition Report

| Conditions Report | Details |
|-------------------------|---------|
| 1. Battery Status | Pass |
| 2. Resting Voltage(V.) | 12.8 |
| 3. Charging Voltage(V.) | 14.9 |

Chassis Report




| Damage Level |
|--------------|
| No Damage |
| Level A |
| Level B |
| Level C |

| | |
|---|------|
| No dent in the under carriage (th) | PASS |
| No deform chassis or chassis frame (th) | PASS |
| No visible corrosion on the chassis or chassis frame (th) | PASS |
| No missing part on the chassis frame (th) | PASS |
| Half cut Analysis (th) | PASS |

















| | |
|----------------------|-----------|
| Chassis Damage Level | No Damage |
|----------------------|-----------|








Interior Inspection Points



| | |
|-----------------------------|---|
| Scratched/Faded items | S |
| Sunken/Sagging car seats | D |
| Tear/Cracks | Y |
| Failed Electrical Equipment | E |

Interior Report

| | |
|---|--|
| 1. Dashboard |  |
| 2. Sound system and monitor |  |
| 3. Air conditioning system |  |
| 4. Console |  |
| 5. Steering wheel and control panel |  |
| 6. Gear knob |  |
| 7. Left Headliner |  |
| 8. Right Headliner |  |
| 9. Left power window master |  |
| 10. Front left door panel |  |
| 11. Front left seat |  |
| 12. Front right seat |  |
| 13. Window control switch, front right door |  |
| 14. Front right door panel |  |
| 15. Right rear power window master switch |  |
| 16. Right rear door panel |  |


| | |
|--|--|
| 17. Left rear power window master switch |  |
| 18. Rear Seat 1 |  |
| 19. Rear Seat 2 |  |
| 20. Rear Seat 3 |  |
| 21. Left rear door panel |  |
| 22. Luggage storage area |  |
| 23. Rear |  |

Vehicle Overview

| | | | |
|--|------|--|------|
| 1. Vehicle Engine Number Analysis (th) | PASS | 14. Air Conditioning and Heating System (th) | PASS |
| 2. Vehicle Chassis Number Analysis (th) | PASS | 15. Front and Rear Suspension (th) | PASS |
| 3. Vehicle Original OEM Color Analysis (th) | PASS | 16. Drive Axle (th) | PASS |
| 4. Engine System (th) | PASS | 17. High Tech (th) | PASS |
| 5. Transmission System (th) | PASS | 18. Passenger Comfort (th) | PASS |
| 6. Electrical System (th) | PASS | 19. Security System (th) | PASS |
| 7. Brake System (th) | PASS | 20. Safety Active (th) | PASS |
| 8. Steering System (th) | PASS | 21. Safety Passive (th) | PASS |
| 9. Fuel System (th) | PASS | 22. Original Mileage Analysis (th) | PASS |
| 10. Four-wheel Drive (th) | PASS | 23. Overall Chassis Analysis (th) | PASS |
| 11. Turbocharger/Supercharger (th) | PASS | 24. Overall Exterior Analysis (th) | PASS |
| 12. Fuel Injection and Engine Management System (th) | PASS | 25. Overall Interior Analysis (th) | PASS |
| 13. Engine Cooling System (th) | PASS | | |

Flood Report

| | |
|-------------------|----|
| Evidence of Flood | No |
|-------------------|----|



Fire Report

| | |
|------------------|----|
| Evidence of Fire | No |
|------------------|----|



Inspector Note

Vehicle : MERCEDES BENZ GLC250

Chassis number : WDC2539096L016417

Inspection date : 2024-07-15

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมพบหลักฐานการซ่อมแซมทำสีมาบ้างชิ้น รื้อรอยรอบคันเล็กน้อย กระจกเป็นรอยสะเก็ดหิน / สภาพยาง4เส้น หน้าปี 22 หลังปี 21 เสื่อมสภาพ ภายใน(Interior) : ภายในปกติ สะอาดเรียบร้อย , อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้สมบูรณ์ครบปกติ เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII พบสิ่งผิดปกติ แนะนำเข้าตรวจเช็คศูนย์บริการ (ไม่ได้ทดสอบขับ) โครงสร้าง(Frame) : อุบัติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE