

Premium Inspection Analysis



Premium Inspection Analysis

Customer Name	: MERCEDES-BENZ MOBILITY (THAILAND) CO., LTD.	Inspection Date	: 2024-09-11
Tel.	:	Lemon Inspection ID	: LEMON24090096
Inspector	:แทนรัก ทิพย์อินทร์	Approved By	: Sakulpong S

Details

Brand	MERCEDES BENZ	Model year	2019
Model	GLA250	Engine Code - No.	27092031899344
Sub-model	AMG Dynamic	Registration year	2021-11-09
License Plate		Chassis No.	WDC1569446L013512
Current Mileage(km.)	18842	Engine Capacity(cc.)	2000

Inspection Lists	Grading
1. Exterior	****
2. Chassis	****
3. Interior	****
4. Engine & Mechanical	****
5. Overall	****


This vehicle has been inspected by the SCHIC INSPECTION BY LEMON-AIDE inspection service.

Inspector	แทนรัก ทิพย์อินทร์	Approved By	Sakulpong_S




Premium Inspection Analysis

Vehicle Front Image



Vehicle Back Image





Premium Inspection Analysis

Vehicle Front Left Image



Vehicle Front Right Image






Premium Inspection Analysis

Vehicle Rear Left Image




Vehicle Rear Right Image






Premium Inspection Analysis

Vehicle Registration Book




Vehicle Engine Image





Premium Inspection Analysis

Vehicle Odometer Image



Vehicle Chassis Image






Premium Inspection Analysis

Vehicle Engine Number Image



OBD Vehicle Identity Analysis






Premium Inspection Analysis

OBD Vehicle Health Analysis




Passenger Front Console Image






Premium Inspection Analysis

Passenger Front Seat Image




Passenger Ceiling Part Image





Premium Inspection Analysis


Passenger Back Seat Image





Premium Inspection Analysis

Exterior Inspection Points



Exterior Status		
0	Original	
N	New Parts	
BP	New Body Paint Job	
Χ	Need Replacing	



Premium Inspection Analysis

Exterior Inspection Report

1. Front Skirt	0	14. Left Skirt	0
2. Front Bumper	ВР	15. Left Wing Mirror	0
3. Front Right Fender	BP	16. Front Windshield	0
4. Front Right Wheel	0	17. Roof	0
5. Front Left Fender	BP	18. Rear Right Fender	0
6. Front Left Wheel	0	19. Rear Bonnet	0
7. Front bonnet	ВР	20. Back Right Wheel	0
8. Right Wing Mirror	0	21. Rear Bumper	0
9. Front right door	BP (S1)	22. Rear Skirt	0
10. Rear right door	ВР	23. Rear Left Fender	0
11. Right Skirt	0	24. Back left wheel	O (S1)
12. Rear Left door	BP	25. Back Windshield	0
13. Front left door	BP		

Main Status

BP	New Body Paint Job
N	New Parts
0	Original
Χ	Need Replacing


Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	Е	Dimple
С	Corrosion	F	Paint Fade




Premium Inspection Analysis








Premium Inspection Analysis








Premium Inspection Analysis








Premium Inspection Analysis







Premium Inspection Analysis





Premium Inspection Analysis

Tire Condition Report

Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Worn Down	1019	4
2. Front Right Tire Condition	Worn Down	1019	4
3. Back Left Tire Condition	Worn Down	1019	4
4. Back Right Tire Condition	Worn Down	1019	4










Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.4
3. Charging Voltage(V.)	15.1



Premium Inspection Analysis

Chassis Report



No Damage Level A Level B Level C

No dent in the under carriage	PASS
No deform chassis or chassis frame	PASS
No visible corrosion on the chassis or chassis frame	PASS
No missing part on the chassis frame	PASS
Half cut Analysis	PASS


Chassis Damage Level	No Damage
----------------------	-----------





Premium Inspection Analysis

Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E



Premium Inspection Analysis

Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	



Premium Inspection Analysis

17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	



Premium Inspection Analysis

Vehicle Overview

1. Vehicle Engine Number Analysis	PASS	14. Air Conditioning and Heating System	PASS
2. Vehicle Chassis Number Analysis	PASS	15. Front and Rear Suspension	PASS
3. Vehicle Original OEM Color Analysis	PASS	16. Drive Axle	PASS
4. Engine System	PASS	17. High Tech	PASS
5. Transmission System	PASS	18. Passenger Comfort	PASS
6. Electrical System	PASS	19. Security System	PASS
7. Brake System	PASS	20. Safety Active	PASS
8. Steering System	PASS	21. Safety Passive	PASS
9. Fuel System	PASS	22. Original Mileage Analysis	PASS
10. Four-wheel Drive	PASS	23. Overall Chassis Analysis	PASS
11. Turbocharger/Supercharger	PASS	24. Overall Exterior Analysis	PASS
12. Fuel Injection and Engine Management System	PASS	25. Overall Interior Analysis	PASS
13. Engine Cooling System	PASS		



Premium Inspection Analysis

Flood Report

Evidence of Flood







Fire Report

Evidence of Fire

No







Premium Inspection Analysis

Inspector Note

Vehicle: MERCEDES BENZ GLA250

Chassis number: WDC1569446L013512

Inspection date: 2024-09-11

Inspector : ภายนอก(Exterior) : รถเก็บสีมาบางชิ้น / ริ้วรอยถลอกเล็กน้อย / ล้อแม็กเป็นรอยถลอก / ยางเลื่อม สภาพทั้ง 4 เส้น ปี 19 ภายใน(Interior) : ภายในสะอาดเรียบร้อย ,อุปกรณ์ไฟฟ้า แอร์ วิทยุ ใช้งานได้สมบูรณ์ครบปกติ เครื่องยนต์(Engine) : วิเคราะห์ปัญหาด้วยเครื่อง OBDII ไม่พบสิ่งผิดปกติ (ไม่ได้ทดสอบขับขี่) โครงสร้าง(Frame) :

โครงสร้างหลักปกติ ไม่มีการช่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง

Vehicle Certification: Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE