





Preowned Vehicle Inspection Report

Premium Inspection Analysis


Vehicle Front Image



Vehicle Back Image




Vehicle Front Left Image




Vehicle Front Right Image




Vehicle Rear Left Image



Vehicle Rear Right Image



Vehicle Registration Book



Vehicle Engine Image




Vehicle Odometer Image




Vehicle Chassis Image




Vehicle Engine Number Image




OBD Vehicle Identity Analysis



OBD Vehicle Health Analysis



Passenger Front Console Image



Passenger Front Seat Image




Passenger Ceiling Part Image



Passenger Back Seat Image



Exterior Inspection Points



Exterior Status	
O	Original
N	New Parts
BP	New Body Paint Job
X	Need Replacing

Exterior Inspection Report

1. Front Skirt	O	14. Left Skirt	O
2. Front Bumper	O (S3)	15. Left Wing Mirror	O
3. Front Right Fender	O (S1)	16. Front windshield	O (G2)
4. Front Right Wheel	O (S1)	17. Roof	O
5. Front Left Fender	O	18. Rear right fender	O (D1)
6. Front Left Wheel	O (S1)	19. Rear Bonnet	O
7. Front Bonnet	O	20. Back right wheel	O (S2)
8. Right Wing Mirror	O	21. Rear Bumper	O
9. Front right door	O (S2)	22. Rear Skirt	O
10. Rear right door	O (S1)	23. Rear left fender	O (D1)
11. Right Skirt	O (S2)	24. Back left wheel	O (S1)
12. Rear Left door	O (D1)	25. Back Windshield	O
13. Front left door	O (S1)		

Main Status

BP	New Body Paint Job
N	New Parts
O	Original
X	Need Replacing

Sub Status

S	Scratched	G	Stone Chip on Glass
D	Dent	Y	Cracked
R	Rust	E	Dimple
C	Corrosion	F	Paint Fade

Vehicle Defect Notices



Vehicle Defect Notices



Vehicle Defect Notices




Vehicle Defect Notices




Vehicle Defect Notices



Vehicle Defect Notices







Vehicle Defect Notices



Tire Condition Report


Conditions Report	Tire Status	Date Code	Tire Depth(mm)
1. Front Left Tire Condition	Normal	2123	5
2. Front Right Tire Condition	Normal	2123	5
3. Back Left Tire Condition	Normal	0222	5
4. Back Right Tire Condition	Normal	0222	5



Battery Condition Report

Conditions Report	Details
1. Battery Status	Pass
2. Resting Voltage(V.)	12.9
3. Charging Voltage(V.)	14.6

Chassis Report




Damage Level
No Damage
Level A
Level B
Level C

No dent in the under carriage (th)	PASS
No deform chassis or chassis frame (th)	PASS
No visible corrosion on the chassis or chassis frame (th)	PASS
No missing part on the chassis frame (th)	PASS
Half cut Analysis (th)	PASS











Chassis Damage Level	No Damage
----------------------	-----------








Interior Inspection Points



Scratched/Faded items	S
Sunken/Sagging car seats	D
Tear/Cracks	Y
Failed Electrical Equipment	E

Interior Report

1. Dashboard	
2. Sound system and monitor	
3. Air conditioning system	
4. Console	
5. Steering wheel and control panel	
6. Gear knob	
7. Left Headliner	
8. Right Headliner	
9. Left power window master	
10. Front left door panel	
11. Front left seat	
12. Front right seat	
13. Window control switch, front right door	
14. Front right door panel	
15. Right rear power window master switch	
16. Right rear door panel	


17. Left rear power window master switch	
18. Rear Seat 1	
19. Rear Seat 2	
20. Rear Seat 3	
21. Left rear door panel	
22. Luggage storage area	
23. Rear	

Vehicle Overview

1. Vehicle Engine Number Analysis (th)	PASS	14. Air Conditioning and Heating System (th)	PASS
2. Vehicle Chassis Number Analysis (th)	PASS	15. Front and Rear Suspension (th)	PASS
3. Vehicle Original OEM Color Analysis (th)	PASS	16. Drive Axle (th)	PASS
4. Engine System (th)	PASS	17. High Tech (th)	PASS
5. Transmission System (th)	PASS	18. Passenger Comfort (th)	PASS
6. Electrical System (th)	PASS	19. Security System (th)	PASS
7. Brake System (th)	PASS	20. Safety Active (th)	PASS
8. Steering System (th)	PASS	21. Safety Passive (th)	PASS
9. Fuel System (th)	PASS	22. Original Mileage Analysis (th)	PASS
10. Four-wheel Drive (th)	PASS	23. Overall Chassis Analysis (th)	PASS
11. Turbocharger/Supercharger (th)	PASS	24. Overall Exterior Analysis (th)	PASS
12. Fuel Injection and Engine Management System (th)	PASS	25. Overall Interior Analysis (th)	PASS
13. Engine Cooling System (th)	PASS		

Flood Report

Evidence of Flood	No
-------------------	----



Fire Report

Evidence of Fire	No
------------------	----



Inspector Note**Vehicle :** MERCEDES BENZ E300**Chassis number :** W1K2130536L049992**Inspection date :** 2024-08-08

Inspector : ภายนอก(Exterior) : การตรวจสภาพภายนอกโดยรวมไม่พบหลักฐานการซ่อมแซมทำสี มีริ้วรอยถลอก บูด รอยคัน / ก้นชนหน้าและสเกิร์ตเป็นรอยถลอก /สภาพยางปกติทั้ง4เส้น หน้าปี23 หลังปี22 ภายใน(Interior) : ภายในเบาะหน้าขวามีรอยย่นเล็กน้อย สะอาดเรียบร้อย ,อุปกรณ์ไฟฟ้า แอร์ วิทยุFM ใช้งานได้ตามมาตรฐานครบปกติ

เครื่องยนต์(Engine) : เครื่องยนต์ทำงานได้ปกติ ,วิเคราะห์ปัญหาด้วยเครื่อง OBDII พบสิ่งผิดปกติ รหัสU015902 แนะนำตรวจเช็คเข้าศูนย์บริการ (ไม่ได้ทดสอบขับขี) โครงสร้าง(Frame) : อุบัติเหตุไม่มี ,โครงสร้างหลักปกติ ไม่มีการซ่อมแซมโครงสร้างหรือมีการชนถึงโครงสร้าง หมายเหตุ หน้าปิดรีอนไม่มีไฟโซว เช็ค OBDII พบ โค้ด U015902 สัญญาณ Parktronic ทำงานผิดปกติ แนะนำตรวจเช็คโดยละเอียดอีกครั้ง

Vehicle Certification : Pass the inspection standard of SCHIC INSPECTION BY LEMON-AIDE