

Pre-owned Car Certificate

Mercedes-Benz vehicle are checked comply to Mercedes-Benz Thailand requirements



VIN:W1N2477876L012224Inspection Report No.:144Inspection Date:13/12/2024KM Status:26042

Grading Level				
3A	=	Excellent Condition (No repaint or parts damage)		
Α	=	Good Condition (a parts re-painted or slightly damage)	M	
В	=	Normal Condition (several parts repainted or slightly damage)		
С	=	Poor Condition (medium/heavy accident, no or poor rework)		

17 DEC 2024

Signature / Date On behalf of **BGAC MB Automotive Engineering**

VIN:	W1N2477876L012224
Inspection Report No.:	144
Inspection Date:	13/12/2024
KM Status:	26042

Photo documentation - Exterior



Front Right View



Front Left Side View



Rear Left Side View



Front View



Front Right Side View



Rear View

VIN:	W1N2477876L012224
Inspection Report No.:	144
Inspection Date:	13/12/2024
KM Status:	26042

Photo documentation - Interior




Cockpit



Media Display



Instrument Cluster



Front Entrance



Center Console



Rear Entrance

VIN:	W1N2477876L012224
Inspection Report No.:	144
Inspection Date:	13/12/2024
KM Status:	26042

Photo documentation - Engine / Aggregates



Engine




Underbody





Front Left / Right Axle



Front Left / Right Wheel



Rear Left / Right Axle



Rear Left / Right Wheel

VIN:W1N2477876L012224Inspection Report No.:144Inspection Date:13/12/2024KM Status:26042


Scope of visual check based on MBTh requirements


A. Scope of visual inspection

Visual check of accident / flooding damage / impact on body, paint surface and underbody parts:

Ν	= No damage	
S	= Minor damage	Ø
Μ	= Medium damage	
L	= Large / heavy damage or impact	
Х	= Extra damage or impact	

Damage areas






B. Summarize condition statement

• Rear Right Door – Dent

VIN:	W1N2477876L012224
Inspection Report No.:	144
Inspection Date:	13/12/2024
KM Status:	26042

Photo documentation - Non-Conformities (if any)



Rear Right Door - Dent

