

Pre-owned Car Certificate

Mercedes-Benz vehicle are checked comply to Mercedes-Benz Thailand requirements



VIN: W1N2477876L011531

Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338

Grading Level

3A = Excellent Condition (No repaint or parts damage) □

A = Good Condition (a parts re-painted or slightly damage)

B = Normal Condition (several parts repainted or slightly damage) \Box

C = Poor Condition (medium/heavy accident, no or poor rework)

Latamanda. 17 DEC 2024

Signature / Date

On behalf of BGAC MB Automotive Engineering



Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338

Photo documentation - Exterior



Front Right View



Front Left Side View



Rear Left Side View



Front View



Front Right Side View



Rear View



Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338


Photo documentation - Interior



Cockpit



Instrument Cluster



Front Entrance



Media Display



Center Console



Rear Entrance



Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338

Photo documentation - Engine / Aggregates



Engine



Underbody





Front Left / Right Axle





Rear Left / Right Axle





Front Left / Right Wheel





Rear Left / Right Wheel



Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338


Scope of visual check based on MBTh requirements


A. Scope of visual inspection

Visual check of accident / flooding damage / impact on body, paint surface and underbody parts:

N	=	No damage	
S	=	Minor damage	
M	=	Medium damage	
L	=	Large / heavy damage or impact	
Χ	=	Extra damage or impact	

Damage areas





B. Summarize condition statement

- Front Left Door Light Scratch
- Front Left Door Handle Paint Chip




Inspection Report No.: 141

Inspection Date: 13/12/2024

KM Status: 28338

Photo documentation - Non-Conformities (if any)



Front Left Door - Light Scratch



Front Left Door Handle - Paint Chip

