

Pre-owned Car Certificate

Mercedes-Benz vehicle are checked comply to Mercedes-Benz Thailand requirements



VIN: W1N1671176M016044
Inspection Report No.: 120
Inspection Date: 02/07/2024
KM Status: 14019

Grading Level

- | | | | |
|----|---|---|-------------------------------------|
| 3A | = | Excellent Condition (No repaint or parts damage) | <input type="checkbox"/> |
| A | = | Good Condition (a parts re-painted or slightly damage) | <input type="checkbox"/> |
| B | = | Normal Condition (several parts repainted or slightly damage) | <input checked="" type="checkbox"/> |
| C | = | Poor Condition (medium/heavy accident, no or poor rework) | <input type="checkbox"/> |

Patanamda 10 JUL 2024

Signature / Date

On behalf of **BGAC MB Automotive Engineering**

VIN: W1N1671176M016044
Inspection Report No.: 120
Inspection Date: 02/07/2024
KM Status: 14019

Photo documentation - Exterior




Front Right View



Front View




Front Left Side View



Front Right Side View



Rear Left Side View



Rear View

VIN: W1N1671176M016044
Inspection Report No.: 120
Inspection Date: 02/07/2024
KM Status: 14019

Photo documentation - Interior



Cockpit




Media Display




Instrument Cluster



Center Console



Front Entrance




Rear Entrance

VIN: W1N1671176M016044
Inspection Report No.: 120
Inspection Date: 02/07/2024
KM Status: 14019

Photo documentation - Engine / Aggregates




Engine Room



Underbody



Front Left / Right Axle



Rear Left / Right Axle



Front Left / Right Wheel



Rear Left / Right Wheel

VIN: W1N1671176M016044
 Inspection Report No.: 120
 Inspection Date: 02/07/2024
 KM Status: 14019



Scope of visual check based on MBTh requirements

A. Scope of visual inspection

Visual check of accident / flooding damage / impact on body, paint surface and underbody parts:

- | | |
|------------------------------------|-------------------------------------|
| N = No damage | <input type="checkbox"/> |
| S = Minor damage | <input type="checkbox"/> |
| M = Medium damage | <input checked="" type="checkbox"/> |
| L = Large / heavy damage or impact | <input type="checkbox"/> |
| X = Extra damage or impact | <input type="checkbox"/> |

Damage areas




B. Summarize condition statement


- Engine Hood - Paint Chip
- Chrome Front Bumper Trim - Chip
- Front Right Door - Paint Chip
- Front Left Door - Dent

VIN: W1N1671176M016044
Inspection Report No.: 120
Inspection Date: 02/07/2024
KM Status: 14019


Photo documentation - Non-Conformities (if any)




Engine Hood - Paint Chip



Chrome Front Bumper Trim - Chip



Front Right Door - Paint Chip



Front Left Door - Dent

